



RV-1/RV-1S/RV-1T/RV-2M/RV-2T

Spindles



No.1



No.2



No.3



No.4



No. 0

Specifications:

Model	RV-1	RV-1S	RV-1T	RV-2M	RV-2T
Measurement Range	10-1×100,000 mpa.s/cp			10-2×1,000,000 mpa.s/cp	
Display	LCD				
Spindles Specification	Standard: No. 1, 2, 3, 4 Note: No. 0 spindles is Optional, test 0.1-100 cps				
Rotating Speed of Spindles	6 / 12 / 30 / 60 rpm/min.			0.3 / 0.6 / 1.5 / 3 / 6 / 12 / 30 / 60 rpm/min.	
Optional	No	RS232	1. RS232 Interface And Edit Software 2. Temperature probe (0-100 degree)	RS232	1. RS232 Interface And Edit Software 2. Temperature probe (0-100 degree)
Automatic Switch	free selection of proper rotating speed or spindles number.				
Stable Cursor	Strip-type cursor fully charged displayed when reading basically stable				
Measurement Tolerance	<= ± 5%	<= ± 2%			<= ± 2%
Measurement Repeatability	<= ± 2%	<= ± 1%			<= ± 1%
Power	AC 100-240V/50-60 HZ				
Working Condition	Temperature 5-40 degree Relative humidity no more than 80%				
Attachments	1. No. 1,2,3,4 Spindles 2. No. 0 Spindle is optional 3. Adapter 4. Foundation Plate 5. Up-Down Frame 6. English Manual				
Outline Dimension (mm)	370×325×280 mm				
Packing (mm)	450×420×250 mm				
Net / Gross Weight (kg)	6.8 kg / 9kg				
H.S. Code	9027				

Photos:

